		Sole WE55 and WE95			
7 pii	7 pin harness		10 pin harness		
Vin c	1	Black		1	White
GND_c	2	Brown		2	Gray
+5v	3	Red		3	Purple
VR	4	Orange		4	Blue
GND	5	Yellow		5	Green
UP	6	Green		6	Yellow
DOWN	7	Blue		7	Orange
				8	Red
				9	Brown
				10	Black
Incline Test	t				

Jump pin 1 to pin 6 - UP Jump pin 1 to pin 7 - DOWN

(only use the 7 pin harness)

Resistance Test

Resistance UP Pin 1 of 7 pin harness to pin 9 of 10 pin harness and pin 2 of 7 pin harness to pin 10 of 10 pin harness

Pin 1 of 7 pin harness to pin 10 of 10 pin harness Resistance Down

and pin 2 of 7 pin harness to pin 9 of 10 pin harness